

**Alltyblacca Highway Support**

**Client**

Ceredigion  
County Council

**Location**

Alltyblacca  
Ceredigion

**Date**

2014



The works consisted of supporting an existing gabion wall which was in danger of failure. The gabion wall was supporting a highway and pavement. Soil nails were used to support the gabion walling with steel beams used to span between the soil nails.

- Installation of soil nails by use of a Merlo and man cage.
- Installation of sleeves within existing gabion basket.
- Grouting of soil nails and stress testing.
- Landscaping and fencing works.

